




A




B



Aa		8x20	x8
Ba		8x30	x38
Ca		7x30	x6
E		7x50	x4
Ea		M6x35	x2
Fa		M6x8x15x15	x2
Ga		7x34	x18
Ha		15x12	x18
G		5x38	x31
Ja		5x50	x4
Ka		21x21x16	x2
La		3,5x15	x4
Ma		3x20	x4

Q		3,5x40	x19
Oa		3,5x16	x21
J		4x30	x4
Ra		D19x6	x4
P		D13	x4
Z		D20	x2
M		D4x13	x3
O		D15x18	x2
V		D26	x2
Qa		D35	x4
W		11/5,8x6,5	x4
WS		11/6,2x9	x8
T		4mm	x2
Y		350	x1



1



Aa		8x20	x8
Ba		8x30	x26

2a



A



Ca		7x30	x6
----	--	------	----

2b



B



Ca		7x30	x6
----	--	------	----

3a


A



Y		350	x1
W		11/5,8x6,5	x4

3b


B




Y		350	x1
W		11/5,8x6,5	x4


4a

A




E		7x50	x2
M		D4x13	x1
P		D13	x4

4b




E		7x50	x2	M		D4x13	x1
				P		D13	x4

5a




Ga		7x34	x4
----	---	------	----


5b



Ga		7x34	x4
----	---	------	----







G		5x38	x4
Ha		15x12	x4



G		5x38	x4
Ha		15x12	x4

7

A






Ga



7x34

x4

8




Ha



15x12

x4

9




G



5x38

x2

10



J



4x30

x2

Ka



21x21x16

x2

La



3,5x15

x4

Ha



15x12

x2



Z



D20


x2

11




Ma		3x20	x4
Y		350	x1

12



E		7x50	x2
M		D4x13	x2
V		D26	x2
Oa		3,5x16	x4



13





Fa		M6x8x15	x2
Ea		M6x35	x2
O		D15x18	x2



14




40 - 747x70x17mm 5pcs.




Ra		D19x6	x2
G		5x38	x3
Ja		5x50	x2
Q		3,5x40	x5





15



41 - 780x90x17mm 2pcs.







42 - 780x70x17mm 4pcs.





Ra		D19x6	x2
Oa		3,5x16	x12
G		5x38	x4
Ja		5x50	x2

16






Oa		3,5x16	x5
G		5x38	x10

17



18




Q



3,5x40


x14

19




Ba		8x30	x8
----	---	------	----

20




Ga		7x34	x4
----	---	------	----

21




Ha		15x12	x4
----	---	-------	----

22




G		5x38	x4
J		4x30	x2

23




Ga		7x34	x4
----	---	------	----

24



Ba		8x30	x4
----	---	------	----

25




G



5x38

x4

26




Ha



15x12

x4

27



Qa

WS

WS



WS



11/6,2x9

x8

Qa



D35

x4