








25 min



b







a






A		8x30	x7
B		7x34	x9
C		15x12	x9
D		250mm	x2
E		3,5x15	x8
F		3,5x40	x6
G		45x12	x2
H		19x5,8x6,3	x2
J		D25x3	x2

1





A		8x30	x7
---	--	------	----


2




B		7x34	x8
---	--	------	----


③




D		250mm	x2
E		3,5x15	x4

4a




B		7x34	x1
J		D25x3	x2

4b




B		7x34	x1
J		D25x3	x2

5a




F		3,5x40	x2
---	---	--------	----

5b




F		3,5x40	x2
---	---	--------	----

6a




C		15x12	x1
---	---	-------	----

6b




C		15x12	x1
---	---	-------	----

7a




C		15x12	x4
---	---	-------	----

7b




C		15x12	x4
---	---	-------	----

8




F		3,5x40	x4
---	---	--------	----

9a




C		15x12	x4
---	---	-------	----

9b




C		15x12	x4
---	---	-------	----

10a




H		19x5,8x6,3	x2
---	---	------------	----

10b



H		19x5,8x6,3	x2
---	---	------------	----

11



G		45x12	x2
E		3,5x15	x4