




Assembly Instructions Bea Trundle

1/4



Hardware

A	CSK Screw M4 x 25mm		x 30
B	Caster		x 4
C	CSK Screw M4 x 16mm		x 12
D	L Bracket		x 2
E	CSK Screw M4 x 38mm		x 4


Tool required for assembly :

* Phillips Screwdriver
(not supplied)

Assembly Instructions Bea Trundle

2/4

Part in Box




Parts No	Description	Qty	Carton #
1	Front Panel	1	1/1
2	Back Panel	1	1/1
3	Side Support	2	1/1
4	Bed Slats	1	1/1


Assembly Instructions Bea Trundle

3/4

1




2




Assembly Instructions Bea Trundle

4/4

3

A	CSK Screw M4 x 25mm		x 22
---	------------------------	---	------



4

C	CSK Screw M4 x 16mm		x 12
D	L Bracket		x 2

