




ASSEMBLY INSTRUCTIONS




Component list



Ax1




Bx1




Cx1




Dx1




Ex2




Fx1



Gx1




Hx1



Ix1




Jx1



Kx1




Lx1




Mx1


Hardware list




①x4




②x4



③x4



④x16




M6*50

⑤x2



6*16*1


⑥x2




5mm

⑦x1


1




2



3




4




5







G




6




7



8



9



10

