





A		8x40	x34
B		8x55	x2
C		10x40	x4
D		M6x60	x4
E		M6x10x13	x4
F		7x60	x9
G		D35	x6
H		7x34	x9
J		15x12	x9




K		5x38	x2
L		D4x13	x1
M		D15	x4
N		D35x9	x2
P		M8x20x10,4	x2
Q		M8x20-D28	x2
R		3,5x40	x6
S		D17x3	x12
T		4mm	x1

1




A		8x40	x34
C		10x40	x4

2




F		7x60	x6
---	---	------	----


③




G		D35	x2
S		D17x3	x4

④




G		D35	x2
N		D35x9	x2

⑤




G		D35	x2
S		D17x3	x4


6




H		15x12	x9
---	---	-------	----

7




B		8x55	x2
---	---	------	----

8




J		15x12	x4
K		5x38	x2

9




J		15x12	x4
S		D17x3	x4

10




P		M8x20x10,4	x2
---	---	------------	----

11



Q		M8x20-D28	x2
---	---	-----------	----



12



D		M6x60	x4
E		M6x10x13	x4
M		D15	x4

J		15x12	x1
F		7x60	x3
L		D4x13	x1

13



R



3,5x40

x6